Sydney: (02) 9890 9111
Brisbane: (07) 3715 2200
Melbourne: (03) 9212 4422
Perth: (08) 9373 9999
Adelaide: (08) 9373 9969
sales@machineryhouse.com.au
www.machineryhouse.com.au

Product Brochure For C4640

Hypertherm Powermax105® - Torch Consumables suit

Prior Model with 5 piece consumable stack



Please Call

ORDER CODE:	~
Plasma Machine Model:	~
Plasma Torch Model:	~
Type:	~
Part Number:	~
Size (mm):	~
Pack Quantity:	~
Plasma Torch Type:	~

Description

The Powermax105® plasma system uses a 5 piece stack consumable system

For all Powermax105® cutting consumables, torches & spares please refer to recommended accessories below

Sydney: (02) 9890 9111
Brisbane: (07) 3715 2200
Melbourne: (03) 9212 4422
Perth: (08) 9373 9999
Adelaide: (08) 9373 9969
sales@machineryhouse.com.au
www.machineryhouse.com.au

Product Brochure For C4640

Specific Features



Powermax105



C4640

Recommended Accessories

P8060
Hypertherm Hand Torch



P799
Plasma Water Table Fluid



P837
Hypertherm 30-105A Electrode



P8371
Hypertherm 45-105A Copper Plus Electrode



P838
Hypertherm 45A Nozzle



P839
Hypertherm 65A Nozzle



P840
Hypertherm 85A Nozzle



P841
Hypertherm 105A Nozzle



Sydney: (02) 9890 9111
Brisbane: (07) 3715 2200
Melbourne: (03) 9212 4422
Perth: (08) 9373 9999
Adelaide: (08) 9373 9969
sales@machineryhouse.com.au
www.machineryhouse.com.au

Product Brochure For C4640

P842
Hypertherm FineCut Only Nozzle



P843
Hypertherm 45-85A Swirl Ring



P844
Hypertherm 105A Swirl Ring



P845
Hypertherm 45-85A Shield



P846
Hypertherm 105A Shield



P847
Hypertherm 45-105A Deflector



P848
Hypertherm 65-105A Retaining Cap



P8081
Hypertherm Eliminizer Filter - Replacement filter element



AP0001
Air filter element kit -Internal



AP0005
Hypertherm O-Ring



AP0007
Hypertherm O-Ring Lube




AP0011
Duramax® 180° Torchbody



Sydney: (02) 9890 9111
Brisbane: (07) 3715 2200
Melbourne: (03) 9212 4422
Perth: (08) 9373 9999
Adelaide: (08) 9373 9969
sales@machineryhouse.com.au
www.machineryhouse.com.au

Product Brochure For C4640

AP0016
Duramax® 180° Torch Mounting sleeve



AP0018
Duramax® 180° Torch quick disconnect repair kit



P8452
Hypertherm Shield Drag Cutting Suits Hand Torch



P8472
Hypertherm Deflector Suits Hand Torch



P8431
Hypertherm Swirl Ring Finecut Suits Hand Torch

